



FALC

WARNING

- Do not use flammable or explosive substances using this function in the ultrasonic bath. Be extremely careful with gas. To avoid explosion always use equipment as the manufacturer's instructions specify.
- Do not use acids, alkalis, or other aggressive liquids. If you use aggressive solutions in water containing cleaning liquid in the bath.
- Do not start the liquid in the bath in the water in the bath in the bath. If you start the liquid in the bath in the bath, the water surface should be covered with the cleaning liquid.
- Do not start the work process in the bath in the bath. If you start the work process in the bath in the bath, the water surface should be covered with the cleaning liquid.
- Power supply must have good earthing. Do not use the ultrasonic bath in a wet or damp environment.

Control panel with a digital display showing '88' and several buttons.